User's Guide



THE CENTER FOR NANOSCIENCE AND NANOTECHNOLOGY

MA6 MASK ALIGNER





Machine Overview



Part #	Description	
1	Log book	
2	MAIN POWER SWITCH	
3	Lamp power supply	
4	Analog panel	
5	Digital panel	
6	Microscope	
7	Mask holder	

Part #	Description
8	Mask holder vacuum connector
9	Slide
10	Chuck
11	Chuck positioning micrometers Θ (front), x-axis (rear)
12	Chuck positioning micrometer y-axis
13	Shutter



Lamp Start and Warm Up



Machine Start

Mask Insertion I

Exposure without Alignment I

17	Main screen	Vac-Ct/Cont X1:+25.00 Xr:+25.00 BSA/A1. Gap: 30 V1:+50.00 Yr:+50.00 Ready for Load,
18	 <u>To change Contact PROGRAM</u> Press SELECT PROGRAM Use Y arrows on digital keypad to select program Press SELECT PROGRAM again to exit the menu 	Use Use
19	<u>To change Exposure Time</u> Press <i>EDIT PARAMETER</i> Use Y arrows on digital keypad to change Exposure Time Press <i>EDIT PARAMETER</i> again to exit menu	F1 CMARKE CREEKT CREEKT CREEKT CREEKT SCAN STATE KREEKK CREEKT Hand-Ct-/Cont Exp. Time[s]: Hand-Ct-/Cont Exp. Time[s]: BSR/Al. Gap: 45 Use ARROW keys Ready for Load
20	Press <i>LOAD</i> Gently pull slide out of machine until stop	LOAD UNLOAD Hard-Ct/Cont X :+ 0.00 BSB/Al. Gap: 45 Y :- 0.03 Pull slide and load substrate onto chuck

Exposure without Alignment II

21	 Place substrate on chuck and align to pins on 3", 4" and 6" chuck (4" chuck shown) or grooves on chip chuck (not shown) Do NOT let wafer sit on top of pin! When in doubt, leave a small gap (1 mm or so) between wafer and pins 	Shown: 4" wafer properly aligned to ½ pins
22	When wafer is seated properly, press <i>ENTER</i> To turn on substrate vacuum Gently push slide into machine until stop Press <i>ENTER</i> again Chuck raises automatically	Hard-Ct/Cont X :+ 0.00 BSA/AL Gap: 45 Y :- 0.03 Move slide into machine and Confirm with ENTER Hard-Ct/Cont X :+ 0.00 BSA/AL Gap: 45 Y :- 0.03 Performing WEC ! Please wait
23	Screen reads <i>PERFORMING WEC</i> Make sure substrate is aligned to mask! If possible, align by looking through mask at substrate edges Otherwise, set X micrometer a and Y micrometer b both to 10 mm (center position)	Hand-Ct/Cont X :+ 0.00 B5A/Exe. T.: 1.2 Y := 0.06 Align substrate
24	Double check contact and exposure parameters! Put on UV protective glasses Press <i>EXPOSURE</i>	EXPOSURE

Exposure without Alignment III		
25	Chuck will lower automatically When screen reads <i>Pull slide and unload</i> <i>expose substrate</i>	
	Gently pull slide until stop An audible beep is sounded when substrate vacuum is released	
26	Remove wafer from chuck	
27	Gently push slide into machine until stop	
28	Removing mask 1. Press <i>CHANGE MASK</i> To release vacuum between mask holder and machine 2. Slide mask holder out of machine, flip and place on side tray spacer flags facing UP 3. Press <i>ENTER</i> To release substrate vacuum 5. Insert fingernail into groove a and pull TOWARDS YOU 6. Remove mask from mask holder 7. Press <i>CHANGE MASK</i> 8. Press <i>ENTER</i> To confirm mask holder is not in place, returns to main screen During the day, leave MA6 in this state with Main Screen visible	Image: Content of the second secon
29	Log out on Log Book	

Exposure with Alignment I

30	Main screen	Uac-Ct/Cont X1:+25.00 Xr:+25.00 BSA/Al. Gap: 30 Y1:+50.00 Yr:+50.00 Ready for Load,
31	 <u>To change Contact PROGRAM</u> Press SELECT PROGRAM Use Y arrows on digital keypad to select program Press SELECT PROGRAM again to exit the menu 	Image: Contemporation Image: Contemporation Image: Contemporation Image: Contemporation
32	<u>To change Exposure Time</u> Press <i>EDIT PARAMETER</i> Use Y arrows on digital keypad to change Exposure Time Press <i>EDIT PARAMETER</i> again to exit menu	Hand-Ct/Cont Exp. Time[s]: 1.2 BSA/Al. Gap: 45 Use ARROW keys
33	Press <i>LOAD</i> Gently pull slide out of machine until stop	LOAD UNLOAD Hard-Ct/Cont X :+ 0.00 BSArAl. Gap: 45 Y :- 0.03 Pull slide and load substrate onto chuck

Exposure with Alignment II

34	Place substrate on chuck and align to pins on 3", 4" and 6" chuck (4" chuck shown) or grooves on chip chuck (not shown) Do NOT let wafer sit on top of pin! When in doubt, leave a small gap (1 mm or so) between wafer and pins	Shown: 4" wafer properly aligned to ½ pins
35	When wafer is seated properly, Press ENTER To turn on substrate vacuum Gently push slide into machine until stop Press ENTER again Chuck raises automatically Screen reads PERFORMING WEC	Hard-Ct/Cont X :+ 0.00 BSA/Al. Gap: 45 Y :- 0.03 Move slide into machine and Confirm with ENTER Hard-Ct/Cont X :+ 0.00 BSA/Al. Gap: 45 Y :- 0.03 Performing WEC ! Please wait
36	Press <i>BSA MICROSCOPE</i> Turns off bottom side microscope Turns on top side microscope <i>TSA displayed in main screen</i>	Hard-Ct/Cont X :+ 0.00 Hard-Ct/Cont X :+ 0.00 Align substrate
37	Roughly align substrate to mask View substrate features through mask openings and use <i>X</i> (a) and <i>Y</i> (b) micrometers to align Otherwise set a and b to 10 mm	

b

Exposure with Alignment IV

43	Check wafer/mask separation! Press SEP down button to view separation on screen While adjusting micrometers, minimum Z separation is 20 µm	Hard-Ct/Cont Z LumJ : -45 TSR/Exp. T.: 1.2 Align substrate
44	Adjust X, Y and θ (a , b and c) micrometers to align substrate to mask	
45	Rotate microscope objectives to 10X to evaluate alignment (if necessary)	
46	Press SEP up button to raise chuck and evaluate alignment (if necessary) <u>Caution!</u> Do <u>NOT</u> adjust micrometers if Z separation is below 20 µm! If re-alignment is required Press SEP down button until screen reads 20 µm	
47	When alignment is achieved Double check contact and exposure parameters! Put on UV protective glasses Press <i>EXPOSURE</i>	Hard-Ct/Cont X :+ 0.00 TSA/Exp. T.: 1.2 Y :- 0.06 Align substrate

	Exposure with Ali	ignment V
	Chuck will lower automatically	
48	When screen reads <i>Pull slide and unload</i> <i>expose substrate</i>	
	Gently pull slide until stop	
	An audible beep is sounded when substrate vacuum is released	
49	Remove wafer from chuck	
50	Gently push slide into machine until stop	
	Removing mask	
	1. Press <i>CHANGE MASK</i> To release vacuum between mask holder and machine	F3 CHANGE LAMP- TEST
	2. Slide mask holder out of machine, flip and place on side tray spacer flags facing UP	SELECT PROGRAM PROGRAM PRAVILETER
	3. Press <i>ENTER</i> To release substrate vacuum	SCAN
51	5. Insert fingernail into groove a and pull TOWARDS YOU	KT - K
	6. Remove mask from mask holder	
	7. Press CHANGE MASK	
	8. Press <i>ENTER</i> To confirm mask holder is not in place, returns to main screen	
	During the day, leave MA6 in this state with Main Screen visible	Uac-Ct/Cont X1:+25.00 Xr:+25.00 BSA/A1. Gap: 30 Y1:+50.00 Yr:+50.00 Ready for Load,
52	Log out on Log Book	
	MA6 User's Guide I4	December 201

